



REBOOT² SIZE CHART



CENTIMETERS

HELMET
SIZE

57-58 M

59-60 L

61 XL

HOW TO MEASURE

A HEAD CIRCUMFERENCE

Using a measuring tape, measure the head circumference at the head's widest point, just above the eyebrows and the ears.

